

Product Change Notice

Huawei PCN ALD-20170003

33 type Antenna Products EOM

Release History

Version	Revision History	Release Date
Rev: A Draft	Draft Release	2017-07-31
Rev: A	Official Release	2017-07-31

Contents

1. Key Terms	3
2. Abstract	3
3. PCN Information	5
4. Reason for Change.....	5
5. Systems and Products Affected.....	5
6. BOM Code Affected	6
7. Change Description	8
7.1 Changes in Specifications.....	8
7.2 Changes in Appearance.....	8
7.3 Changes in Dimensions and Weight.....	8
7.4 Changes in the External Ports of a Module	8
7.5 Changes in the Installation Method.....	8
8. Compatibility	8
9. Change Impact.....	8
10. Changes in the Documentation.....	9
11. Other Changes.....	9
12. Suggestions for Operators	9
13. Attachments.....	9
14. Remarks.....	9

Product Change Notice

1. Key Terms

Terminology	Description	Definition
EOM	End of Marketing	The date after which orders for products, boards, components or software are no longer accepted  NOTE This applies to new deployments and capacity expansions. For boards and components, it also applies to spare parts.
LODSP	Last Order Date of Spare Parts	The date after which orders for spare parts of a product are no longer accepted
PCN	Product Change Notice	Describes changes to a product.

2. Abstract

Marketing of the following Huawei's antenna products will be discontinued on Feb 20, 2018. After this date, orders for these antenna will no longer be accepted.

Model	BOM	Description
A704517R1	27012074	DX-690-960-65-17.5i-M-B/R
AMB4520R1v06	27011934-002	2MXX-790-960/1710-2200-65/33-16i/19.5i-M/M-R
ADU4515R0v01A2	27011729	DXX-790-862/880-960-65/65-14.5i/15i-M/M-R
ADU4516R0v01A2	27011728	DXX-790-862/880-960-65/65-16i/16.5i-M/M-R
ADU4517R0v01A2	27011727	DXX-790-862/880-960-65/65-17i/17.5i-M/M-R
ATR451715	27011455	DXXX-790-960/1710-2180/1710-2180-65/65/65-15i/17.5i/17.5i-M/M/M
ADU451720v06	27011411-001	DXX-790-960/1710-2180-65/65-17.5i/18i-M/M
ATR4518R2v01	27011410-001	DXXX-790-862/880-960/1710-2690-65/65/65-15.5i/16i/18i-M/M/M-R
ADU4518R5v06	27011337-001	DXX-1710-2170/2490-2690-65/65-18i/18i-M/M-R
A79451503v06	27011154-001	DX-790-960-90-15i-M
ADU4518C1	27011135-001	DXX-790-960/1710-2180-65/65-16.5i/18.5i-M/M-C
ADU4517C0	27011134-001	DXX-790-960/1710-2180-65/65-15i/17.5i-M/M-C
ADU4518C0	27010996-001	DXX-790-960/1710-2180-65/65-17.5i/18.5i-M/M-C

ATR4516F1	27011096-001	DXXX-790-960/1710-2180/1710-2180-65/65/65-16.5i/16.5i/16.5i-M/M/M-ESLS/F
ADU4518F1	27011095-001	DXX-790-960/1710-2180-65/65-16.5i/18.5i-M/M-ESLS/F
ATR4517F1	27011094-001	DXXX-790-960/1710-2180/1710-2180-65/65/65-17.5i/17.5i/17.5i-M/M/M-ESLS/F
ADU4518F2	27011093-001	DXX-790-960/1710-2180-65/65-17.5i/18.5i-M/M-ESLS/F
ATR451612	27011050-001	DXXX-790-960/1710-2180/1710-2180-65/65/65-16.5i/16.5i/16.5i-M/M/M-ESLS
ADU451820	27011014-001	DXX-790-960/1710-2180-65/65-16.5i/18.5i-M/M-ESLS
ATR451713	27011013-001	DXXX-790-960/1710-2180/1710-2180-65/65/65-17.5i/17.5i/17.5i-M/M/M-ESLS
ADU451821	27011012-001	DXX-790-960/1710-2180-65/65-17.5i/18.5i-M/M-ESLS
ADU4516R7	27012200	DXX-790-960/790-960-65/65-16i/16i-M/M-R
ADU451617	27011967	DXX-790-960/790-960-65/65-16i/16i-M/M
ADU4517R2	27011607-001	DXX-690-960/690-960-65/65-17.5i/17.5i-M/M-R
ADU4516R2	27011702-001	DXX-690-960/690-960-65/65-16.5i/16.5i-M/M-R
A90451702v01	27010987-001	DX-790-960-65-17i-0F
ADU451901	27010814	DXX-1710-2690/1710-2690-65/65-19.5i/19.5i-M/M
A26451900	27010811	DX-1710-2690-65-19.5i-M
A19452103	27010761	DX-1710-2170-65-21i-2F
A19452102	27010687	DX-1710-2170-33-21i-0F
A19451703	27010654	DX-1710-2170-90-17i-M
A19452101	27010652	DX-1710-2170-33-21i-M
A19452100	27010650	DX-1710-2170-65-21i-0F

This change notice is for customers who use the antenna.

3. PCN Information

PCN Number			ALD-20170003
Supplier Information			Huawei Technologies Co., Ltd.
PCN Classification			DN
Milestone	Implementation date	The start date when new boards or components or new changes are available.	NA
	EOM	The date when orders for old components are no longer accepted.	2018/02/20
	EOS	Date after which Huawei no longer provides services for old hardware	NA

4. Reason for Change

33 type antenna products reached the product lifecycle, orders for the antenna will no longer be accepted

5. Systems and Products Affected

System	Subsystem	Hardware	Software
Antenna Feeder Products	Antenna	Yes	NA

6. BOM Code Affected

New Board/Component			Old Board/Component			Complete Replacement
BOM Code	Model	Description	BOM Code	Model	Description	
/	/	/	27012074-002	A704517R1v06	DX-690-960-65-17.5i-M-B/R	/
27011934-001	AMB4520R2v06	2MXX-690-960/1710-2200-65/33-16i/19.5i-M/M-R	27011934-002	AMB4520R1v06	2MXX-790-960/1710-2200-65/33-16i/19.5i-M/M-R	/
/	/	/	27011729	ADU4515R0v01A2	DXX-790-862/880-960-65/65-14.5i/15i-M/M-R	/
/	/	/	27011728	ADU4516R0v01A2	DXX-790-862/880-960-65/65-16i/16.5i-M/M-R	/
/	/	/	27011727	ADU4517R0v01A2	DXX-790-862/880-960-65/65-17i/17.5i-M/M-R	/
/	/	/	27011455	ATR451715	DXXX-790-960/1710-2180/1710-2180-65/65/65-15i/17.5i/17.5i-M/M/M	/
27010881-004	ADU451807v06	DXX-790-960/1710-2180-65/65-17.5i/18.5i-M/M	27011411-001	ADU451720v06	DXX-790-960/1710-2180-65/65-17.5i/18i-M/M	/
27011410-002	ATR4518R2v06	DXXX-790-862/880-960/1710-2690-65/65/65-15.5i/16i/18i-M/M/M-R	27011410-001	ATR4518R2v01	DXXX-790-862/880-960/1710-2690-65/65/65-15.5i/16i/18i-M/M/M-R	/
/	/	/	27011337-001	ADU4518R5v06	DXX-1710-2170/2490-2690-65/65-18i/18i-M/M-R	/
/	/	/	27011154-001	A79451503v06	DX-790-960-90-15i-M	/
/	/	/	27011135-001	ADU4518C1	DXX-790-960/1710-2180-65/65-16.5i/18.5i-M/M-C	/
/	/	/	27011134-001	ADU4517C0	DXX-790-960/1710-2180-65/65-15i/17.5i-M/M-C	/
/	/	/	27010996-001	ADU4518C0	DXX-790-960/1710-2180-65/65-17.5i/18.5i-M/M-C	/
/	/	/	27011096-001	ATR4516F1	DXXX-790-960/1710-2180/1710-2180-65/65/65-16.5i/16.5i/16.5i-M/M/M-ESLS/F	/
/	/	/	27011095-001	ADU4518F1	DXX-790-960/1710-2180-65/65-16.5i/18.5i-M/M-ESLS/F	/
/	/	/	27011094-001	ATR4517F1	DXXX-790-960/1710-2180/1710-2180-65/65/65-17.5i/17.5i/17.5i-M/M/M-ESLS/F	/

New Board/Component			Old Board/Component			Complete Replacement
BOM Code	Model	Description	BOM Code	Model	Description	
/	/	/	27011093-001	ADU4518F2	DXX-790-960/1710-2180-65/65-17.5i/18.5i-M/M-ESLS/F	/
/	/	/	27011050-001	ATR451612	DXXX-790-960/1710-2180/1710-2180-65/65/65-16.5i/16.5i-M/M/M-ESLS	/
/	/	/	27011014-001	ADU451820	DXX-790-960/1710-2180-65/65-16.5i/18.5i-M/M-ESLS	/
/	/	/	27011013-001	ATR451713	DXXX-790-960/1710-2180/1710-2180-65/65/65-17.5i/17.5i-M/M/M-ESLS	/
/	/	/	27012200	ADU4516R7	DXX-790-960/790-960-65/65-16i/16i-M/M-R	/
/	/	/	27011967	ADU451617	DXX-790-960/790-960-65/65-16i/16i-M/M	/
/	/	/	27011607-001	ADU4517R2	DXX-690-960/690-960-65/65-17.5i/17.5i-M/M-R	/
/	/	/	27011702-001	ADU4516R2	DXX-690-960/690-960-65/65-16.5i/16.5i-M/M-R	/
/	/	/	27011012-001	ADU451821	DXX-790-960/1710-2180-65/65-17.5i/18.5i-M/M-ESLS	/
/	/	/	27010987-001	A90451702v01	DX-790-960-65-17i-0F	/
/	/	/	27010814	ADU451901	DXX-1710-2690/1710-2690-65/65-19.5i/19.5i-M/M	/
/	/	/	27010811	A26451900	DX-1710-2690-65-19.5i-M	/
/	/	/	27010761	A19452103	DX-1710-2170-65-21i-2F	/
/	/	/	27010687	A19452102	DX-1710-2170-33-21i-0F	/
/	/	/	27010654	A19451703	DX-1710-2170-90-17i-M	/
/	/	/	27010652	A19452101	DX-1710-2170-33-21i-M	/
/	/	/	27010650	A19452100	DX-1710-2170-65-21i-0F	/

7. Change Description

7.1 Changes in Specifications

None

7.2 Changes in Appearance

None

7.3 Changes in Dimensions and Weight

None

7.4 Changes in the External Ports of a Module

None

7.5 Changes in the Installation Method

None

8. Compatibility

None

9. Change Impact

Safety Risks	NA
Fire Risks	NA
Services	NA
Communications	NA
Maintenance	NA
Reliability	NA
Power System/Power Consumption	NA
Traffic	NA

10.Changes in the Documentation

Antenna&AF products datasheet

11.Other Changes

None

12.Suggestions for Operators

None

13.Attachments

None

14.Remarks

If you have any questions about this PCN, contact your local Huawei sales representative or Huawei technical support.